

Quick Start

Do not leave the battery and booster unattended while in use. Do not operate the unit near water. It is the users responsibility to follow battery mfg. suggested charging rate. Users must also closely monitor the pack temperature during fast charging. Overcharging may occur if the Torpedo malfunction or, when user does not follow battery mfg. recommended charge rate. Never connect the booster to less than 4cell or more than 7cell. This unit is not intended for use by unsupervised children. This booster is designed for R/C car high power Ni-Cd & Ni-MH battery only. When charging, also monitor the temperature of the booster. If the unit becomes too hot, disconnect the unit.



110-120V AC CORD INPUT CONNECTION



BOOSTER OUTPUT CONNECTION



PRESS START AND BOOSTING BEGIN



ANALYZING AND PROCESSING FOR 20s



BOOSTING DURATION IS APPROX 5MIN